



Photograph of subject structure before/during rehabilitation, camera facing northeast



Photograph of subject structure after rehabilitation, camera facing northeast





Photograph of subject structure after rehabilitation, camera facing southeast