



Facing north toward the property from N. Market St.



Facing the proposed parking area from the railroad right-of-way.





Typical cabin façade.



Facing the rear of the property from the railroad right-of-way.





Sample condition of original cabin.



Sample condition of original cabin.