



Subject property before rehabilitation, camera facing north



Subject property before rehabilitation, camera facing northwest



Former canopy and accessory structure, camera facing north



Detail of west façade before rehabilitation, camera facing northeast

455 So Academy



Facade view after rehabilitation, camera facing north



Detail view from rear after rehabilitation, camera facing south

455 So Academy



Detail view of west facade after rehabilitation, camera facing northeast



Detail view of east facade after rehabilitation, camera facing northwest