



Vehicle stopped in northwest-bound right-turn lane on Willowbrook at FM 1101 to pick-up child(ren)



Vehicle turning around after child pick-up at front of subdivision. Roadway is blocked temporarily.



Cars parked on either side of Willowbrook in front of the model home (721 Willowbrook). Road is wide enough for a third vehicle to drive through between them.



Visual of roadway width and current state of sidewalk at front of subdivision. Gap is visible on the southeast side of Willowbrook.



Pavement width measured at 36 feet at entrance of subdivision where road is striped for 3 lanes.
Pavement width further within subdivision measured at 30 feet.